## Why does my PAL TV-Tuner stop functioning as soon as DirectX 9.0b is installed?

Changes to DirectX in version 9.0b have adversely affected the functionality of the PAL TV-Tuner. Microsoft are currently working hard to resolve the issue.

The following is an excerpt from a statement that Microsoft has released, as found on ATI's web site: <a href="http://mirror.ati.com/support/infobase/4254.html">http://mirror.ati.com/support/infobase/4254.html</a>

Microsoft has investigated reports that the DirectX 9.0b release adversely affects a subset of ATI products with PAL TV Tuners. We acknowledge that a change to DirectShow TV Tuner support in this 7/25/03 release has impacted PAL TV capture. We are developing a patch with high priority to correct this issue. Please note that this change is not related to the security fix identified in bulletin MS03-030, although both fixes are in the DirectX 9.0b release.

The Patch is now available at Microsoft's site:

http://www.microsoft.com/downloads/details.aspx?familyid=8dfd1b6d-e177-4a0e-91d0-b4310675b02b&displaylang=en