

I have installed the latest driver and firmware version for my DJ Console and the headphone previewing is no longer working with Virtual DJ.

As indicated on the [Download page](#), when installing the latest DJ Console MK2 driver, you also need to apply the latest update for Virtual DJ (Version 3.4.1). This will allow your DJ Console to be recognized and used properly by the software.

This update is available on [Virtual DJ's web site](#) (registration of the software using the provided serial number is required).